





INDUSTRIAL VALVES AUTOMATION

Pekos Pekos P Pekos Pekos Pekos Pekos P s Pekos Pekos Pekos Pekos P Pekos Pekos Pekos Pekos P Pekos Pekos Pekos Pekos P s Pekos Pekos Pekos Pekos P Pekos Pekos Pekos Pekos P s Pekos Pekos Pekos Pekos P Pekos Pekos Pekos Pekos P

s Pekos Pekos

Pekos Pekos P

Pekos Pekos

Pekos Pekos

Pekos Pekos P



ESDV Emergency Shut-Down Valve

General Features

- ON-OFF valve intended for emergency situations. Long periods of time at the same position (opened) until an emergency happens.
- · Required stroking times, specially for safety position.
- Single acting actuators. FAIL CLOSE.
- · Manual reset pneumatic valves.
- Pneumatic control configuration: 1001, 1002.
- PST / SIL / Hazardous locations.
- · Fire Protection Coating
- An ESDV valve is controlled by the Emergency Shut-Down system (ESD).
- A SDV valve is controlled by the Process Safety System (PSS).




BDV Blow-Down Valve

General Features

- · Valve intended for venting the pipe line.
- Assembled with an air tank to ensure valve availability during emergency situations.
- Required stroking times.
- Single acting actuators. Fail open.
- Pneumatic control configuration: 1001, 2002.
- · Hazardous locations.
- A BDV valve is controlled by the Emergency Shut-Down system (ESD).



Pressure Switch Gauge Lock-Up valve Check Valve Drain Valve Safety Valve





XV Valve Process Valve

General Features

- ON-OFF valve controlled by the Process Control System (PCS).
- Required stroking times.
- Single acting / double acting actuators.
- Pneumatic control configuration: 1001, 1002, 2002, etc.
- PST.
- SIL.
- Hazardous locations.




MOV Motorized Valve Process Valve

General Features

- ON-OFF controlled valve by PCS
- 230/400 VAC Power. 230 VAC/24 VDC Control
- Hazardous Locations
- SIL
- HART
- Stroking Times



ASSEMBLY, TESTING AND REPORT DOCUMENTS



Functional Test Report Sheet sample













www.pekos.es

Sales & Headquarters:

Rec del Molinar, 9 - P.I. El Circuit 08160 Montmeló (Barcelona) - Spain

Bildosola industrialdea 48142 Artea (Vizcaya) - Spain

Tel.: (+34) 93 568 92 56 / Fax: (+34) 93 579 92 44



Pekos Pekos Pekos Pekos s Pekos Pekos Pekos Pekos

Pekos Pekos Pekos Pekos

Pekos Pekos

Pekos Pekos

pekos@pekos.es