



IRON AND STEEL

Blast Furnace, LD Converter and Electric Arc Furnace



ENGLISH	FRANCAIS	DEUTSCH	ENGLISH	FRANCAIS	DEUTSCH
1 Feed hoppers	Trémies de chargement	Baschickungstrichter	10 Casting drills	Forets de perçage	Abstichdorn
2 Cowper valves	Vannes de cowpers	Cowper-Schieber	11 Decompression valves	Vannes de décompression	Druckminderschieber
3 Skip rollers	Galets de skips	Laufrollen	12 Blower valves	Soupapes de soufflantes	Schieber
4 Skip interiors	Parois intérieures de skips	Möllerwagen	13 Wagon wheels	Roues de wagons	Radatz
5 Tuyares	Tuyères	Winddüsen	14 L.D. nozzles	Lances L-D	Mundstück für "L-D" Lance
6 Blowpipes	Brusillons	Hochofendüse	15 L.D. manifolds	Coudes de lances L-D	Rohrkrümmer "L-D"
7 Small bells	Petites cloches	Gichtglocke	16 Electrode holders	Lames de cisailles	Elektrodenhalter
8 Large bells	Grandes cloches	Grosse Glocke	17 Electrode holder slides	Pincas porte-électrodes	Klemmbacke
9 Rotary hoppers	Trémies tournantes	Drehtrichter			